Flexit Orientation Tool User Guide

- Introduction
- Theory of operation
- Software Installation:
- Tool Setup
- Starting a Survey
- Data Retrieval and Processing
- Appendix 1: Using the offline geomagnetic field calculator software
- Appendix 2: Guidelines for "suspicious" tool readings
- Appendix 3: Disabling the tools in case of explosives work on the rig floor
- · Appendix 4: Flexit file types, locations and extensions
- Appendix 5: creating the "Mega-Sync" file
- Appendix 6: Battery Life Considerations


Introduction

The Flexit tool orients advanced piston corer (APC) cores by taking orientation measurements for a short period of time just prior to when the core is taken. The drill string is kept steady while the tool measures and stores measurements from a triaxial magnetometer and a triaxial accelerometer. The data output includes hole ID, dip, azimuth, temperature, magnetic tool face, magnetic field strength, magnetic dip, and accelerometer output. The orientation tool is run on the APC bottom-hole assembly (BHA) within a nonmagnetic core barrel. The tool is synchronized with a PC computer and the Measurelt software before deployment. After deployment the recorded data are downloaded to the the PC via wireless communication.

Theory of operation

Earth's total magnetic field strength varies at any particular point on Earth. The field is characterized by six parameters: declination, inclination, horizontal intensity (north and east components), vertical intensity, and total intensity. Magnetic field strength values increase toward the poles but only change minimally with borehole depth. Declination is the angular difference between true (geographic) north and magnetic north. Inclination is the angle at which the magnetic field lines intersect the surface of the earth (ranging from 0° at the Equator to 90° at the poles).

The core orientation process determines the angular correction to apply to the core's declination values as measured by the cryogenic magnetometer. The Flexit tool is connected to the core barrel in such a way that the double lines on the core liner are at a fixed known angle to the sensors. The Flexit tool records an azimuth to magnetic north for each core. This azimuth combined with the local magnetic declination values allows the scientists to correct the measured core declination's back to the true coordinates.



The Flexit tool and brass pressure case kit.

Software Installation:

If you are installing the software on a new computer, you must register the tools after installing the Flexit software, version 3.5 (on the TAS/Software volume). Click the Set-Up button, then click the Tool Set-up and Register SmartTool buttons respectively. Type in the serial number and registration codes for each tool one at a time and then click Register This. The tool(s) will then be available for you to select when setting up for a run. Ignore any screens about sending off the registration information.

IODP Flexit Tool Information

s/n	Reg. number
0936	D1AA8F4A9B1
0937	9A952918021

Tool Setup

After arriving on site the technician will edit the default survey data to reflect the proper geomagnetic values for the area:

- 1. Get the latitude and longitude of the location from the Bridge and go to the website http://www.ngdc.noaa.gov/geomagmodels/struts /calcIGRFWMM where a calculator will provide the proper values. If the Internet is not available, please see Appendix 1.
- 2. Open MeasureIT, press Set-up (Figure 1) and then Default Survey Data (Figure 2) buttons to edit the Magnetic Field and Dip values for the magnetic Integrity Check (MagIC) and enter the default survey data.
- 3. Use the slider down on the left hand side to access the other portions of the window (Figure 3). Hit Apply when the default information has been set when finished to return to the main menu.
 - a. Default Survey Data is also where measurement units and intervals are set.
- 4. Use The Tool Setup button (Figure 2) to set your default file location for surveys as well as enable Time-Based Continuous Survey (TBCS) mode (Figure 4).

MeasureIT (v3.50	0.0750) - Main	Х
	<u>S</u> et-Up	General / System settings; SENSIT settings; Default Survey data; and Locality database. About and Version History.
<u>/</u> _	S <u>u</u> rvey sessions	Start a new multi-shot survey session on SENSIT.
F L E X I T	Download	Download data from SENSIT or STOREIT No survey sessions available to download from SENSIT
	Work with Surveys	Edit, Calculate, Rename, Delete and Merge Survey Files. Extract surveys from Single Shot databases.
	<u>H</u> elp (F1)	Summary help about available options.
	E <u>x</u> it	Exit and close MeasureIT. You can also use the [X] in the top right of this window.

Figure 1

MeasureIT (v3.50.0750) - S	etup Tool / System / Survey Header	×					
<u>General / system</u> General options, decimal places for data display, DisplayIT location and linking, program language).							
Tool set-up Set up the operating requirements for the SMARTTOOL (Serial Port, Mode, etc.)and SMARTTOOL REGISTRATION.							
Default Survey Data							
Locality Data	Locality Data Maintain database of locality information: Location; Country; Local co-ordinate system; and MagIC values.						
<u>A</u> bout	Version history Exit						
	us, WARNING: You may lose data which is not downloaded. n Mode Actual						

Figure 2

MeasureIT (v3.5	60.0750) - Edit header for"DEF	AULT: "	×
Survey I	Name DEFAULT		
DEFAULT: :	Survey conventions —		<u></u>
Dip Angle	O Horizontal	Dip Positive 💿 Up 🕥 Down	
	C 0 Vertical		
	Elevation Positive	🖸 Up 🔿 Down	
	Linear units	🕑 Metres 🛛 🔿 Feet	
	Angular units	🖲 Degrees 🛛 🔿 Grad	
	Temperature units	💽 Centigrade 🔘 Fahrenheit	
	Co-ordinate system	💽 0 North 🛛 🔿 0 South	
	Locality Not Used	•	
	Location and Country, MagIC	vrovide Locality specific data: Linear/Angular units, values and Local co-ordinate system. «/RITES ANY EXISTING VALUES FOR THESE	
Apply		<u>C</u> ancel	Help (F1)

Survey Name DEFAULT Project Exp 375 Coatton Hisrongi Subduction Margin Country Client Name IDDP Client Reference Survey QW Beth Novak Survey Company Drill Company Drill Company Drill Company Drill Rg Drill Diameter Magnetic Variation Degrees EAST of north Run Survey on Rods Mireline Comments Conditions Apply Cancel Help (f Magnetic Integrity Check (MagiC) Magnetic Field 31600 1000 nanoTesia Magnetic Cip 23 1.5 Degrees Maximum Permitted Curvature 0.0 Cancel Help (f	MeasureIT (v3.50	.0750) Lui		DENTOLIT				
Project Exp 375 Location Hiturangi Subduction Margin Country ODP Client Reference Surveyed By Beth Noval Surveyed by Beth Noval Survey Company Drill Company Drill Company Drill Company Drill Company Drill Company Drill Diameter Magnetic Variation 0 Degrees EAST of north Run Survey on Rods Comments Conditions Comments Conditions Conditions Conditions Apply Queet Help (I M MeasureIT (v2.00) - Edit header for "DEFAULT: " Survey Name DEFAULT Survey Name DEFAULT OEFAULT: Survey Name DEFAULT V Use Magnetic Integrity Check (MagC) Magnetic Integrity Check (MagC) Magnetic Integrity Check (MagC) Magnetic Field 31600 1000 Magnetic Field 3160 1000 Magnetic Fi	Survey Na	ame DEFAU	ULT		-			
Location Hikurangi Subduction Margin Country Client Name IODP Client Reference Surveyed By Beth Novak Survey Company Drill Company Cancel Help (Magnetic Integrity Check (MagiC) Magnetic Entegrity Check (MagiC) Magnetic Entegrity Check (MagiC) Magnetic Field 31600 1000 nanoTesla Magnetic Coordinates in Regional system X (East) 0.0 Metres Local Origin co-ordinates in Regional system X (East) 0.0 Metres Local Y axis name Local Y axis name	DEFAULT: :	Survey He	ader Info	mation -				
Country Client Name DDP Client ID Client Name DDP Client ID Client Name DDP Client Name DDP Client Name Survey GP Beth Novak Survey Company Drill Company Cancel Tele Cancel Help (Magnetic Integrity Check (Magic) Magnetic Field 31600 1000 nanoTesia Magnetic Dip 28 1.5 Degrees Maximum Permitted Curvature (0.0 Degrees Coal Origin co-ordinates Coal Origin co-ordinates Coal Origin co-ordinates Coal Origin co-ordinates Coal V axis name Coal V ax				800 C L 10				
Client Name DDP Client ID Client Reference Surveyed By Beth Noval Survey Company Drill Rig Drill Company Drill Rig Drill Diameter O Magnetic Variation O Degrees EAST of notth Run Survey on Rods Wireline Comments Conditions Conditions Cancel Help (I MeasureIT (V2.00) - Edit header for "DEFAULT: " Survey Name Cancel Survey Name DEFAULT ✓ DEFAULT: Magnetic Integrity Check (Local Co-ordinate Sottings- ✓ Use Magnetic Integrity Check (MagIC) Magnetic Regres are values that you can use to check the quality of your magnetic data and, there are 3 values you can use: 1) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. ** Leave an tem blank to prevent checking of that tem ** Mid value +/- Limit Magnetic Field 31600 1000 panoTesia Maximum Permitted Curvature 0.0 degrees / metre 0.0 Degrees V (North) 0.0 Metres Local X axis name 0.0 Degrees			Hikurangi Sut	oduction Marg	in			
Client Reference Surveyed By Beth Novaki Survey Company Drill Company Drill Company Drill Company Drill Company Drill Diameter Magnetic Variation 0 Degrees EAST of north Run Survey on Rods Comments Conditions Apply Cancel Help (I MeasureIT (v2.00) - Edit header for*DEFAULT: * Survey Name DEFAULT - - DEFAULT: Magnetic Integrity Check (MagIC) Magnetic Integrity Check (MagIC) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. * Lave an item blank to prevent checking of that item *** * Magnetic Field 31600 1000 Magnetic Clip jaz 1.5 Degrees Amagnetic Clip jaz Magnetic Field 31600 Magnetic Dip jaz 1.5 Degrees Calculate results in Local co-ordinates Anguereit Clip jaz 1.5 Degrees		Country						
Surveyed By Beth Novaki Survey Company Drill Company Drill Diameter Drill Company Magnetic Variation 0 Degrees EAST of north Run Survey on Rods Run Survey on Rods Wireline Through bit Comments Conditions Cancel Help (I Apply Cancel Help (I East) Cancel MeasureIT (v2.00) - Edit header for"DEFAULT: " Survey Name DEFAULT ✓ OEFAULT: Magnetic Integrity Check / Local Co-ordinate Settings- ✓ ✓ ✓ Use Magnetic Integrity Check (MagIC) settings are values that you can use to check the quality of your magnetic data and, therefore, Azimuth. There are 3 values you can use: 1) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. ** ✓ Magnetic Field 31600 1000 nanoTesia Magnetic Dip 28 1.5 Degrees Conditate systems X (East) 0.0 Metres Local X axis name 0.0 Degrees	CI	ient Name	IODP			Client ID		
Survey Company Drill Company Drill Diameter Magnetic Variation 0 Degrees EAST of north Run Survey on Rods Rods Wireline Conditions Apply Amounts Conditions Apply Cancel Apply Cancel Help (I Apply Cancel Help (I Apply Cancel Help (I Apply Cancel Help (I Amount of the area of the adder for 'DEFAULT: '' Survey Name DEFAULT DEFAULT: Magnetic Integrity Check (MagIC) Magnetic Integrity Check (MagIC) Magnetic Integrity Check (MagIC) Magnetic Field	Client	Reference						
Drill Company Drill Diameter Magnetic Variation O Degrees EAST of north Run Survey on Rods Rods Wireline Through bit Comments Conditions Apply Quercel Help (I MeasureIT (v2.00) - Edit header for "DEFAULT: " Survey Name DEFAULT V Use Magnetic Integrity Check (MagIC) Magnetic Field 31600 1000 Person Magnetic Dip 28 1.5 Degrees Maximum Permitted Curvature 0.0 degrees / metre Calculate results in Local co-ordinates Angular difference between 0.0 Call Origin co-ordinates in Regional system co-ordinate systems </td <td>Su</td> <td>rveyed By</td> <td>Beth Novak</td> <td></td> <td></td> <td></td> <td></td> <td></td>	Su	rveyed By	Beth Novak					
Drill Rig Drill Diameter Magnetic Variation Burgetic Variation Comments Conditions Apply MeasureIT (v2.00) - Edit header for "DEFAULT: " Survey Name DEFAULT DEFAULT: Magnetic Integrity Check (MagIC) Magnetic Integrity Check (MagIC) <td< td=""><td>Survey</td><td>Company</td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	Survey	Company						
Drill Diameter Degrees EAST of north Run Survey on Rods Wireline Through bit Comments Conditions Cancel Help (I Apply Qancel Help (I MeasureIT (v2.00) - Edit header for "DEFAULT: " Survey Name DEFAULT Image: Conditions Image: Conditions Amage: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Conditions Image: Condition: Conditis condition: Con	Drill	Company						
Magnetic Variation 0 Degrees EAST of north Run Survey on Rods Wireline Through bit Comments Conditions Apply Cancel Help (I Apply DefAult I Help (I Ap		Drill Rig						
Run Survey on Rods Wireline Through bit Comments Conditions Apply Cancel Help (I Apply Cancel Magnetic Integrity Check (MaglC) Magnetic Integrity Check (MaglC) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. * Leave an item blank	Drill	Diameter						
Comments Conditions Cancel Help (I Apply Cancel Help (I Apply Cancel Help (I MeasureIT (v2.00) - Edit header for"DEFAULT: " Image: Conditions Survey Name DEFAULT Image: Conditions DEFAULT: Magnetic Integrity Check / Local Co-ordinate Settings Image: Condition Image: Condition Image: Condition Magnetic Integrity Check (MaglC) Magnetic Integrity Check (MaglC) Magnetic Integrity Check (MaglC) Image: Condition Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. Image: Condition Magnetic Field Magnetic Dip 28 1.5 Degrees Magnetic Dip 28 1.5 Degrees Maximum Permitted Curvature 0.0 degrees / metre 0.0 Degrees Local Origin co-ordinates in Regional system Coal/X axis name 0.0 Degrees V (North) 0.0 Metres Local Y axis name 0.0 Degrees	Magnetic	· Variation	0 Deg	grees	EAST of north			
Conditions Apply Cancel Help (I A MeasureIT (v2.00) - Edit header for "DEFAULT: " Survey Name DEFAULT Image: Condition of the set of the	Run S	Survey on	C Rods	(Wireline	C Through bit		
Apply Cancel Help (I A MeasureIT (v2.00) - Edit header for "DEFAULT: " Survey Name DEFAULT Image: Comparison of the section of the secti	Comments	-						
M MeasureIT (v2.00) - Edit header for "DEFAULT: " Survey Name DEFAULT OEFAULT: Magnetic Integrity Check / Local Co-ordinate Settings Imagnetic Integrity Check (MagIC) Magnetic Integrity Check (MagIC) settings are values that you can use to check the quality of your magnetic data and, therefore, Azimuth. There are 3 values you can use: 1) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. ** Leave an item blank to prevent checking of that item ** Magnetic Dip 28 Magnetic Dip 28 Magnetic Dip 28 Maximum Permitted Curvature 0.0 degrees / metre Calculate results in Local co-ordinates Angular difference between co-ordinate systems X (East) 0.0 Y (North) 0.0 Metres Local Y axis name	Conditions							
 MeasureIT (v2.00) - Edit header for "DEFAULT: " Survey Name DEFAULT DEFAULT: Magnetic Integrity Check / Local Co-ordinate Settings Vise Magnetic Integrity Check (MagIC) Magnetic Integrity Check (MagIC) settings are values that you can use to check the quality of your magnetic data and, therefore, Azimuth. There are 3 values you can use: 1) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. * Leave an item blank to prevent checking of that item ** Magnetic Field 31600 1000 nanoTesla Magnetic Dip 28 1.5 Degrees Maximum Permitted Curvature 0.0 degrees / metre Calculate results in Local co-ordinates Angular difference between co-ordinate systems X (East) 0.0 Metres Local Y axis name Local Y axis name 	nohu						Canaal	Holp /Ff
Survey Name DEFAULT DEFAULT:: Magnetic Integrity Check / Local Co-ordinate Settings ✓ Use Magnetic Integrity Check (MagIC) Magnetic Integrity Check (MagIC) settings are values that you can use to check the quality of your magnetic data and, therefore, Azimuth. There are 3 values you can use: 1) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. ** Leave an item blank to prevent checking of that item ** Magnetic Field 31600 Magnetic Dip 28 Magnetic Dip 28 Maximum Permitted Curvature 0.0 Maximum Permitted Curvature 0.0 Magnetic Dip 28 Maximum Permitted Curvature 0.0 Maximum Permitted Curvature 0.0 Magnetic Dip 28 Maximum Permitted Curvature 0.0 Maximum Permitted Curvature 0.0 Magnetic Dip 28 Local Origin co-ordinates in Regional system Co-ordinate systems X (East) 0.0 Wetres Local X axis name Local Y axis name Local Y axis name	Z bbiy						Cancer	Tieth (L
Magnetic Integrity Check (MagIC) settings are values that you can use to check the quality of your magnetic data and, therefore, Azimuth. There are 3 values you can use: 1) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. ** Leave an item blank to prevent checking of that item ** Mid value +/- Limit Magnetic Field 31600 1000 nanoTesla Magnetic Dip 28 1.5 Degrees Maximum Permitted Curvature 0.0 degrees / metre Calculate results in Local co-ordinates Local Origin co-ordinates in Regional system X (East) 0.0 Metres Local X axis name V (North) 0.0 Metres V (North) 0.0								
Magnetic Integrity Check (MagIC) settings are values that you can use to check the quality of your magnetic data and, therefore, Azimuth. There are 3 values you can use: 1) Magnetic field strength; 2) Magnetic field dip and 3) Maximum permitted curvature. ** Leave an item blank to prevent checking of that item ** Mid value +/- Limit Magnetic Field 31600 1000 nanoTesla Magnetic Dip 28 1.5 Degrees Maximum Permitted Curvature 0.0 degrees / metre Calculate results in Local co-ordinates Local Origin co-ordinates in Regional system X (East) 0.0 Metres Local X axis name V (North) 0.0 Metres V (North) 0.0	Survey I		AULT		-	e Settinas		(
Magnetic Field 31600 1000 nanoTesla Magnetic Dip 28 1.5 Degrees Maximum Permitted Curvature 0.0 degrees / metre Calculate results in Local co-ordinates Angular difference between co-ordinate systems 0.0 Degrees X (East) 0.0 Metres Local X axis name Local Y axis name 0.0 Degrees	Survey I	Name DEF# : Magnetic	AULT c Integrity	Check / Lo	-	e Settings		(
Magnetic Field 31600 1000 nanoTesla Magnetic Dip 28 1.5 Degrees Maximum Permitted Curvature 0.0 degrees / metre Calculate results in Local co-ordinates Angular difference between co-ordinate systems 0.0 Degrees X (East) 0.0 Metres Local X axis name Local Y axis name 0.0 Degrees	Survey I DEFAULT: Use Mage Magnetic Integ therefore, Az There are 3 v	Name DEFA : Magnetic netic Integri grity Check (I imuth. alues you ca	AULT <mark>c Integrity</mark> ity Check (M /lagIC) setting n use: 1) Mag	Check / Lo lagIC) s are values t inetic field stre	cal Co-ordinate hat you can use to ength; 2) Magnetic f	check the quality of y		
Maximum Permitted Curvature 0.0 degrees / metre Calculate results in Local co-ordinates Angular difference between co-ordinate systems 0.0 Degrees X (East) 0.0 Metres Local X axis name 0.0 Degrees Y (North) 0.0 Metres Local Y axis name 0.0 0.0	Survey I DEFAULT: Use Mage Magnetic Integ therefore, Az There are 3 v	Name DEFA : Magnetic netic Integri grity Check (I imuth. alues you ca	AULT c Integrity ity Check (M lagIC) setting n use: 1) Mag revent checki	Check / Lo lagIC) is are values to metic field stre- ing of that item	hat you can use to	check the quality of y		
Calculate results in Local co-ordinates Angular difference between co-ordinate systems 0.0 Degrees Local Origin co-ordinates in Regional system Local X axis name Local X axis name 0.0 Degrees Y (North) 0.0 Metres Local Y axis name 0.0 Degrees	Survey I DEFAULT: Use Mage Magnetic Integ therefore, Az There are 3 v	Name DEFA : Magnetic netic Integri grity Check (I imuth. alues you ca em blank to p	AULT c Integrity ity Check (M /lagIC) setting n use: 1) Mag revent checki	Check / Lo lagIC) s are values to metic field strong of that iten Mid value	that you can use to angth; 2) Magnetic f	check the quality of y ield dip and 3) Maxim		
Local Origin co-ordinates in Regional system X (East) 0.0 Metres Local X axis name V (North) 0.0 Metres Local Y axis name	Survey I DEFAULT: Use Mage Magnetic Integ therefore, Az There are 3 v	Name DEFA : Magnetic netic Integri grity Check (1 imuth. alues you ca em blank to p Mag	AULT c Integrity ity Check (M ilagIC) setting n use: 1) Mag revent checki gnetic Field	Check / Lo lagIC) is are values t inetic field strr- ing of that iten Mid value 31600	that you can use to ength; 2) Magnetic f 1 ** +/- Limit 1000	check the quality of y ield dip and 3) Maxim		
Local Origin co-ordinates in Regional system co-ordinate systems 0.0 Degrees X (East) 0.0 Metres Local X axis name Y (North) 0.0 Metres Local Y axis name	Survey I DEFAULT: Use Mage Magnetic Inter therefore, Az There are 3 v ** Leave an it	Name DEFA : Magnetic netic Integri grity Check (1 imuth. alues you ca em blank to p Mag M	AULT c Integrity ity Check (M ifagIC) setting n use: 1) Mag revent checki gnetic Field agnetic Dip	Check / Lo lagIC) is are values t instic field stre- ing of that iten Mid value 31600 28	that you can use to ength; 2) Magnetic f 1 ** +/- Limit 1000 1.5	check the quality of y ield dip and 3) Maxim nanoTesla Degrees		
	Survey I DEFAULT: Use Mage Magnetic Inter therefore, Az There are 3 v ** Leave an it	Name DEFA : Magnetic netic Integri grity Check (1 imuth. alues you ca em blank to p Mag M	AULT c Integrity ity Check (M ifagIC) setting n use: 1) Mag revent checki gnetic Field agnetic Dip	Check / Lo lagIC) is are values t instic field stre- ing of that iten Mid value 31600 28	that you can use to ength; 2) Magnetic f 1 ** +/- Limit 1000 1.5	check the quality of y ield dip and 3) Maxim nanoTesla Degrees		
	Survey I DEFAULT: Use Magi Magnetic Integ therefore, Az There are 3 v " Leave an it Maximum Maximum Calculate Local Or X (Eas	Name DEFA : Magnetit netic Integri grity Check (1 imuth. alues you ca em blank to p Mag M n Permitted results in I igin co-ordi at) [0.0	AULT c Integrity ity Check (M MagIC) setting n use: 1) Mag revent checki gnetic Field agnetic Dip I Curvature Local co-ord nates in Reg	Check / Lo lagIC) s are values t inetic field strring of that iten Mid value 31600 28 0.0	that you can use to ength; 2) Magnetic f *** +/- Limit 1000 1.5 degrees / n Angu m	check the quality of y ield dip and 3) Maxim nanoTesla Degrees netre	um permitted o	
Apply	Survey I DEFAULT: Use Magi Magnetic Integ therefore, Az There are 3 v " Leave an it Maximum Maximum Calculate Local Or X (Eas	Name DEFA : Magnetit netic Integri grity Check (1 imuth. alues you ca em blank to p Mag M n Permitted results in I igin co-ordi at) [0.0	AULT c Integrity ity Check (M MagIC) setting n use: 1) Mag revent checki gnetic Field agnetic Dip I Curvature Local co-ord nates in Reg	Check / Lo lagIC) s are values t inetic field strring of that iten Mid value 31600 28 0.0	teal Co-ordinate hat you can use to ength; 2) Magnetic f ** 1000 1.5 degrees / n Angu m Local X axis n	check the quality of y ield dip and 3) Maxim nanoTesla Degrees netre	um permitted o	curvature.
ALLOW BALLEN AND A REPORT OF	Survey I DEFAULT: Use Magi Magnetic Integ therefore, Az There are 3 v " Leave an it Maximum Maximum Calculate Local Or X (Eas	Name DEFA : Magnetit netic Integri grity Check (1 imuth. alues you ca em blank to p Mag M n Permitted results in I igin co-ordi at) [0.0	AULT c Integrity ity Check (M MagIC) setting n use: 1) Mag revent checki gnetic Field agnetic Dip I Curvature Local co-ord nates in Reg	Check / Lo lagIC) s are values t inetic field strring of that iten Mid value 31600 28 0.0	teal Co-ordinate hat you can use to ength; 2) Magnetic f ** 1000 1.5 degrees / n Angu m Local X axis n	check the quality of y ield dip and 3) Maxim nanoTesla Degrees netre	um permitted o	curvature.

Figure 3 Default Survey Data screens. The left most window displays the proper default survey settings including units, the middle screen is where a user will enter the expedition, location, and other header information, and the right most window is where a user will enter the MagIC settings. Note that these different windows are accessed by sliding the bar on the left side of the screen in MeasureIT.

	Register SmartTool	Registe	r o <u>n</u> -line	Registration info
Tool	Settings			
		Operation Mode	Actual	
		Comm. Port		Total time: 27:18:24
	N	leasurement Interval	6 seconds	10101 01110. 21.10.24
	llow Time Based Continuous	s Surveying mode (only	switch on if you k	mow what this is!)
	llow Time Based Continuous	s Surveying mode (only	switch on if you H	(now what this is!)
r Folde	ere Information about TBOO er for new survey files	s Surveying mode (only	switch on if you H	know what this is!)
- Foldo S <u>e</u> l	ore Information about TB80	s Surveying mode (only	switch on if you H	know what this is!)
- Foldo S <u>e</u> l	ere Information about TD80 er for new survey files —— ect	s Surveying mode (only	switch on if you h	know what this is!)
- Foldo S <u>e</u> l	ere Information about TD80 er for new survey files —— ect	s Surveying mode (only	switch on if you I	know what this is!)
- Foldo S <u>e</u> l	ere Information about TD80 er for new survey files —— ect	s Surveying mode (only	switch on if you H	know what this is!)

Figure 4 Specifying file location for your surveys and enabling time based continuous survey mode.

Starting a Survey

1. Have your unjacketed tool with batteries installed within a 5-10 meter line of sight to the TransIT PC adapter attached to the computer's serial port.

2. From the MeasureIT main menu (Figure 1), press the Survey Sessions button. Select your tool's serial number (printed on the tool casing) from the list and hit Continue (Figure 5).

M MeasureIT (v3.50.0750) - OPENING COMMUNICATIONS [Actual]							
SensIT: Opening Communications on COM1							
Please select the serial number of the SensIT or StoreIT device for this operation. CHECK THE NUMBER ON THE DEVICE BEFORE SELECTING.	0937 0936	E <u>x</u> it					
Press [Continue] when ready.							

Figure 5 Communications initialization window

3. Verify that the tool is talking by clicking **Measure Angles**. (Most likely the data will make little sense inside the ship because of all the steel but the tool should be at least measuring and reporting.) Move the tool around and ensure that Measure Angles reports the changes. If not, make sure you are linking with the right too!! Our tools are stored close to each other and may also link if selected incorrectly, depending on your location.

4. Click the radio button for Time-based continuous survey as indicated in Figure 6. Select Continue/Initialize tool when finished.

a. Note that at a minimum 6 seconds between shots you have about 27 hours to acquire data before the memory fills up. Our tools have been run as long as 25 hours without incident, but it may be advisable to pull them every 8-12 hours to avoid too much data loss in case of problems.




Figure 6 Tool check/survey type selection screen

5. You will be presented with a window telling you that it's time to start your synchronization file for depths. We do not have to create this file just yet; it will be used during the processing phase though.

6. Additional windows appear with status information about tool initialization; hit Continue if everything is okay.

7. Give the survey a name, such as "{Site}-{Hole}-{start core}-{end core}" or similar (Figure 7). Verify that the measurement units are correct. The other fields should be ignored. Hit Continue when finished.

- a. Note that "the clock is ticking" so avoid starting a survey hours before handing the tool to the Core Techs (CT's).
- b. Once the survey has started, the window will appear as in Figure 8.

MeasureIT (v3.50.0750) - SENSIT Survey Details [Act	tual] 🛛 🗙
Survey Name Site-Hole-X-Y	Operation Mode
Time Resert Continuous Survey	
SURVEY DATA IS BEING RECORDED.	Easting 0.0
You MUST enter the name for this survey.	Northing 0.0
You may also enter the start co-ordinates and/or change the measurement units for this survey.	Elevation 0.0
When ready press [Continue] to go to the Measuring status screen.	
Measurement units	
Linear measurements are Metres Angular measurements are Degrees	Change <u>U</u> nits
Quit	<u>H</u> elp (F1) <u>C</u> ontinue

Figure 7 Survey naming and unit selection screen




Figure 8 Real-time measurement status screen

8. The tool is now ready to go. Place it in its brass pressure case, snug up the end pieces and turn it over to the Core Tech (Figure 9A-B).



Figure 9A: Insert the tool into the pressure case's open end as shown (keyway out)



Figure 9B: slide the key end of the other end seal onto the Flexit tool, insert it into the barrel and tighten. Hand the assembly to the Core Tech for final rigging with the snubber shock and IODP pressure case.

9. Keep track of the times that the tool is on bottom. Stand pipe pressure data and the time on deck for each core can be used to determine when the tool was on bottom. Standpipe pressure peaks just before the core barrel is fired into the sediment, so the orientation period is ~5 minutes before the peak. Please see an ET or Ops Supervisor for a demonstration on accessing the standpipe pressure data.

Data Retrieval and Processing

This version of the software can only do one thing at a time when performing continuous surveys, so you won't be able to configure another tool on the same computer while the first tool is still waiting to have its survey ended. Therefore, if orientation continues and you need a second tool to give to the CT's then it will have to be configured on a different computer that is also running the Flexit software and has a TransIT transceiver attached. Then it can be measuring while you download the data on the first tool from the starting computer. We have a site license for the software, so it can be installed on as many PC's as necessary, but only three TransIT radio-sync devices exist.

We have found through experience that it is preferable to download all of the survey data from the tool, process it, and then put it into a spreadsheet instead of pre-selecting exact data windows based on the driller's worksheet. That allows the user to look at the entire data set and not potentially miss anything by assuming the orientation data window is exactly the same as a given time on bottom (TOB) from the driller. Sometimes the actual orientation windows may be a minute or more different than the time listed by the driller due to factors such as typos or core barrel rotation late in the orientation period.

- 1. After receiving the tool from the CT's, unload the tool from its brass pressure case and keep it within a 5 meter line-of-sight of the TransIT adapter to the computer. Return to the measurement screen (Figure 8) and click End Survey. An option to download the data follows.
- 2. A confirmation screen appears to make sure you really want to finish the survey (Figure 10). Select End Survey Session.

M END SURVEY: Site-Hole->	(-ү 🔀
Do you want to ?	
	Not available for Time Based Continuous Surveys.
Start another survey	interavaliable for thise based continuous surveys.
<u>Continue this survey</u>	and return to survey measurement.
End Survey Session	after which you must retrieve the tool and download the data.

Figure 10 End survey confirmation screen

3. Click Start Download to begin the data download (Figure 11). You'll need to select your tool from the list as before.

a. It takes about a half-second per shot for the data to download, e.g. an 8-hour survey at 6 sec/shot should take around 40 minutes to download. The downloading survey window will be displayed throughout the download process (Figure 12).

Download survey data file is: MS0937-00016.sdf Summary of survey session Survey Instrument SENSIT Tool Serial Number 0937 Date and time of survey(s) 1/19/2009 2:59:45 PM First survey is Site-Hole-X-Y Number of surveys in tool 1	MeasurelT	(v3.50.0750) - Download Select [Actual]		X
Survey Instrument SENSIT Tool Serial Number 0937 Date and time of survey(s) 1/19/2009 2:59:45 PM First survey is Site-Hole-X-Y Number of surveys in tool 1 Help (F1) Image: Site Site Site Site Site Site Site Site	Download s	urvey data file is: MS0937-00016.	sdf	
Tool Serial Number 0937 Date and time of survey(s) 1/19/2009 2:59:45 PM First survey is Site-Hole-X-Y Number of surveys in tool 1 Help (F1) Image: Site State St		Г Summary of survey session———		
Date and time of survey(s) 1/19/2009 2:59:45 PM First survey is Site-Hole-X-Y Number of surveys in tool 1		Survey Instrument	SENSIT	
First survey is Site-Hole-X-Y Number of surveys in tool 1		Tool Serial Number	0937	
Number of surveys in tool 1		Date and time of survey(s)	1/19/2009 2:59:45 PM	
Help (F1)		First survey is	Site-Hole-X-Y	
		Number of surveys in tool	1	
	Holp (F	:1)		
<u>Start download</u>			<u>S</u> tart download	
Quit	Quit			

Figure 11 Start the download process




Figure 12 Download-in-progress screen

4. After downloading the data processing screen appears (Figure 13). This is where you will select the synchronization file.

Survey na	me/ID Site	-Hole-X-Y			Start time 1		:59:45 PN		nterval 6 ecords 55	
Data Filters-										
		window	Magr	etics filter	Mid value	+/- limi	t			
🗹 Gravity filte	ar 1G +/-	0.020	🗖 🗖 F	ield strength	999999	1000			Ap	ilters
			E F	ield dip	-75.0	1.5				
					13.0	1.5			(I los this times
Depth / Time	e reference	file								Use this time
<u>B</u> rowse/s	elect	Not selected								stamp for you
Apply Dep	th / Time									Synch file.
	-	_			-					Synen me.
Manual	Record	Elapsed	Depth	Gravity	Mag.Str.	Mag.Dip		Direction	Status	
selection	0	-		- 0.99835	72364	-10.96	68.42	63.62		
Select All	1			- 0.99657	72576	-10.90	68.94	62.50		
Deselect All	2			- 0.99783	72600	-10.85	69.02	62.55		
Beederederan	3			- 0.99709	72601	-10.87	69.03	62.58		
nstructions:	4			- 0.98417	72461	-11.30	91.77	90.01		
t least ONE ecord must be	5			- 0.99269	72966	-12.13	91.26	89.18		
elected & depth	6			- 0.99772	73002	-12.25	91.23	89.13		
entered to allow	7			- 0.99742	73002 72953	-12.23	91.26 91.23	89.13		
rocessing.	8			- 0.99604 - 1.06077	83393	-12.22	91.23	89.19 53.68	GF	
xternal: Select	10			- 0.99839	70209	-33.18	85.84	350.35	Gr	
depth - time	11			- 0.99839	70209	-10.10	85.89	350.58		
ile and click Apply Depth /	12			- 0.99367	69055	-10.15	91.56	350.58		
ime] button.	12			- 0.99613	68196	-10.43	91.30	349.01		
	14			- 1.01345	57684	-9.03	99.02	186.10		
lanual: Click lecord number	15			- 0.99604	59023	-8.11	101.95	185.54		
ell to select or	16			- 1.03046	57706	-7.63	101.44	185.49	GF	
eselect record.	17			- 0.99367	68084	-22.21	85.33	166.85		
lick Depth cell add or edit	18			- 0.99416	68351	-21.74	85.35	166.19		
epth.	19			- 0.99642	71677	-12.25	83.96	104.17		
	20			- 0.99435	71754	-12.12	83.96	104.14		-

Figure 13 Preliminary downloaded data screen

5. Select **Browse/select** under the Depth/Time reference file heading and navigate to the megasync.txt file. This file is usually found on the C drive in a folder called Core Orientation. If the megasync file does not already exist, refer to Appendix 5 for instructions on creating a new megasync file.

6. Click Apply Depth/Time.

7. Scroll down the data window. You will see your windows of interest highlighted in green. Any suspect data that fails the non-optional Gravity check (1G +/- 2%) will be flagged in lighter green with red text.

8. Click the **Process Selected Records as Survey (Figure 13)**. A file named {your survey name}_FLT.svy is created. This will calculate the values for Magnetic Tool Face (MTF), the primary information IODP uses to orient cores, as well as a variety of other data.

9. Proceed to the Multishot Calculation Stage 1 screen (Figure 14). Click the 'Do not review' button to skip the data review screens. They are of limited use to us because we are not performing a "traditional" downhole survey..

M MeasureIT (v3.50.0750) - Multishot Calculation Stage 1	×
Review survey raw data	
Do you want to review the raw measurements for survey	<u>R</u> eview
This allows you to Select/De-select measurements for calculation and/or change individual station depths.	Do <u>n</u> ot review
Number of "blocks" of same-station measurements 4	
Number of unallocated "blocks" 4	
Number of de-selected measurements 0	
	<u>S</u> kip remaining
	Holp
	<u>H</u> elp

Figure 14 Stage 1 calculation options screen

10. The final screen will reveal the results of the survey (**Figure 15**). You can review both the raw and processed survey files by navigating to the file location you specified as shown in Fig. 1B. All files are in ASCII text despite the file type suffix (.rsy=raw survey, .svy=data-reduction results, .csy=continuous survey, .dtf=depth/time file). Select **Continue**.

M MeasurelT (v3.50.0750) - Data Quality Checks									
1253A-9H-16H_FLT: Quality Check status as indicated:-								:-	
<u>R</u> emove	Station	Dip	Grav.Field	Azimuth	Mag.Field		Status	?	Total 4 Failed 0
Azimuth:	9.0 10.0	88.55 88.56	0.9970	171.02 171.04		-11.0 -11.0			T diled 0
	11.0	120.26 22.62		321.14 205.23					
Ch <u>a</u> nge	12.0	22.02	0.3372	205.23	41034	-50.5			
									<u>C</u> ontinue
									<u>H</u> elp (F1)
	Τ.	11 "	1 1/	10		""			1 \

Figure 15 Final results (for our purposes, "Station" = measurement every 6 seconds)

11. The next step is to calculate out the number of the first station that should be very close to the orientation window for each core. Consider that station numbers in a survey file are time proxies, i.e. each station represents 6 seconds. You can get the tool initialization time and date from either the raw or processed survey file (in GMT since IODP workstations are set to that zone). It may be easier to convert the time to local ship's time for the processing step and to recollect the timing of some operational details that may pertain to the orientation data.

Example: tool start time (from the raw survey file) was 5:25 am local or 0525 hours. According to the standpipe pressure data and time on deck, the tool was on bottom and orienting at 0737 hours for core 3H, 0853 hours for core 4H, and 1012 hours for core 5H. The time difference from tool initialization to core 3H is 132 minutes. Multiply by 10 shots/minute since our tools measure every 6 seconds and you get 1320 measurements taken before you should see your orientation window begin. Similarly, there is 76 minutes between time-on-bottom (TOB) for core 3H and 4H, so add 760 to core 3H's starting point of 1320. Your window for core 4H should start around station #2080. Finally, core 5H's window will be around station #2870 since there were 79 minutes or 790 shots between core 4H and 5H.

12. Copy the data portion of the processed survey file (*_FLT.svy) into Excel and parse it. Hide or delete columns of no interest such as Easting, Northing, Elevation, UpDown, LeftRight, Shortfall, ToolRoll, and DLS.

Optional - for ease of scanning apply conditional formatting to the Temperature, Magnetic Field and Gravitational Field columns: change cell's color if temperature is below 3° C (your bottom hole temperatures may be higher), Mag. Field is less than 50000 nT (check field model for your location and add a 'fudge-factor' for the drillstring) and Gravity is less than .980 or greater than 1.02. Scroll down the processed survey file to the station numbers you calculated in step 10. You should see very repeatable data particularly in the MTF, temperature, and magnetic dip fields. Suspect gravitational field measurements will have changed color from conditional formatting making them easy to delete from the total records to be averaged. Average your 'clean' records and provide the MTF value to the paleomagnetists. Consider keeping a table with other statistics such as the standard deviation, number of readings averaged, and approximate time spent orienting for each core.

Appendix 1: Using the offline geomagnetic field calculator software

This calculator uses a model for the geomagnetic field from 1900 to 2010. It will not allow you to enter a date after 2010.

- 1) Copy the software from TAS/Software/labsystems/Flexit/geomagnetic field calculator/Geomag61_windows folder to your local PC.
- 2) Double-click the Geomag.exe program in your new folder.
- 3) Follow the onscreen prompts. Enter IGRF10.cof for your model, although either model should give similar results for our purposes.
- 4) Choose option 2, month, year and day for the date entry.
- 5) Choose 1, single date for the range option.
- 6) Enter the year, month and day as requested.
- 7) Select option 1, Geodetic coordinates.
- 8) Select option 2, meter units.
- 9) The geodetic altitude above mean sea level (AMSL) is zero, of course!

10) Select whichever mode of latitude/longitude notation you prefer, then enter your coordinates. Winfrog or the bridge is a good place to locate this information.

11) The results are then calculated. For our tool configuration purposes you should make a note of F (total field in nanoTesla; you can safely round to the nearest 500) and Dip. You might also make a note of the individual magnetic field vectors X, Y and Z for occasional comparison with the raw data from the tool.

12) Follow the onscreen prompts to quit or calculate more values.

Appendix 2: Guidelines for "suspicious" tool readings

- Tool motion indications: According to Flexit, a reading is considered suspect if it exceeds ±2% of 1 gravity.
- Absurdly high or low magnetic field readings: readings more than 20000 nT above the values for the location (derived in Appendix 1) may
 indicate that the tool is either faulty or may not be centered in the non-magnetic collar. Low values are probably from faulty magnetometers
 inside the tool. Keep in mind that magnetic field and dip will be considerably higher than normal for your location due to the presence of the
 drillstring, but you can still obtain usable orientations.
- Excessive variation of calculated results within a time window for orientation:
 - Manually scan the file above and below the supposed time period for more consistent results. The time window you were given may be incorrect (typos/transcription errors in the times). Conditional formatting in Excel is a good way to quickly narrow down possible orientation windows.
 - Tool rotated during orientation period. You may be able to find more stable data at the very end of the orientation window. Use the latest stable data for that core.
 - Low battery voltages may cause bad measurements.

 We have occasionally seen "rifling" when apparently good tool results do not apply correctly to all or some sections of the recovered core. This can happen if the tool is stationary and got good results, but the actual core twisted inside the barrel when it fired into the sediment. Remember, orientation is performed *before* the core is shot, not afterwards.

Appendix 3: Disabling the tools in case of explosives work on the rig floor

If there is any question or concern that the radio-frequency transmissions (433MHz, one of two internationally-permitted frequencies for short range radio control) involved with configuring or downloading the Flexit tools may pose a risk to the rigging of explosives for blowing pipe, then do the following:

- 1. Keep the Flexit tools inside their brass pressure cases with the aluminum end caps installed. This should block any communication with the tools from the computer. For absolute certainty, remove the tools' batteries as well. (TO CHECK: does battery-removal blow the memory buffer of survey data??)
- 2. Remove the TransIT PC adapter from the computer's serial or USB port and remove its 9V battery. Be sure you get all Flexit-enabled computers with adapters, there may be up to three of them.

Appendix 4: Flexit file types, locations and extensions

There are a number of files associated with a given survey. Some files are only created after you process the raw survey using the synchronization file. Others are simply log files that you can read for information. Still others are artifacts of a known bug in the software[†] and will cause trouble unless they are deleted after download.

File Type	exten sion	Normal location		
TBCS raw survey file as downloaded from tool (magnetometer and accelerometer raw data, battery voltage, tool temperature)	*.csy	Your default file location in the Flexit software (Fig. 1b)		
TBCS synchronized raw survey file	*_FLT .rsy	Created post-processing at the same location as your raw .CSY file		
TBCS synchronized processed survey file	*_FLT .svy	Created post-processing at the same location as your raw .CSY file		
Sync file location pointer	*.dtf	Created post-processing at the same location as your raw .CSY file		
†temporary survey data file (created when starting a download)	*.sdf	C:\Documents and Settings\All Users\Application Data\Flexit\MeasureIT		
Survey synchronization file	*.txt	User-selectable location		
MeasureIT.ini (initialization file for Flexit software)		C:\ Documents and Settings\All Users\Application Data\Flexit\MeasureIT		
Measureit_LOG (verbose logs of tool downloads and other user/software interactions)	*.txt	C:\ Documents and Settings\All Users\Application Data\Flexit\MeasureIT		
		(see also .\Logfile Archive for date- and time- stamped older log files)		

† **Important note**: be sure to delete or rename the file extension of this file after downloading a survey to the computer. If you do not do this and send the same tool down for another survey, the next download will contain a copy of the previous survey's data, not your current survey. This is a bug in the current MeasureIT software version. You must delete the .sdf file.

Appendix 5: creating the "Mega-Sync" file

a) Start a new workbook in Excel.

b) You will be filling 2 columns with numbers. The first column is time in seconds per station (our default is 6) and the second column will be station number starting with 0.

c) Increment all subsequent columns: add 6 to the first column and 1 to the second column in the following fashion down to row 16383:

	_				
6	0				
12	1				
18	2				
24	3				
30	4				
36	5				
42	6				
48	7				
54	8				
60	9				
66	10				
72	11				

d) Use the concatenate function in Excel to group the 2 columns together delimited by a semi-colon.

e) Open another workbook. The first row must contain "SynchTime=MM/DD/2009 HH:mm:ss" with no quotation marks.

- f) Paste-special (values only) the concatenated data column in your first workbook.
- g) Save the file as Text. It is now ready to use as a synchronization file of any size you need for your survey.

Appendix 6: Battery Life Considerations

There are two batteries of concern when running surveys: the actual tool battery itself and the battery inside the TransIT transceiver. Both battery voltages must be monitored to avoid losing survey data.

The tool battery consists of three CR123 lithium camera batteries attached together and encased in heat-shrink tubing with a small wire harness and 2prong connector. Battery voltage from the pack can be 9.5V or better if the individual batteries are very fresh. The battery in the transceiver is a standard 9V alkaline cell.

Extensive bench testing demonstrates that the tool batteries will last for a very long time (**Figure 16**), but experience has shown that it's advisable to change the battery when the voltage *during a survey* reads approximately 8.5 volts. The tool battery resting voltage is displayed when you first set up a survey (**Figure 6**). However, a more accurate assessment of the tool voltages are found in the raw survey file (*.csy file). That file will give the user a much better idea of the actual state of the battery when in use downhole. Scan the raw file after each survey or plot voltage vs. station number (i.e. time) during data reduction.

As a standard operating procedure each TransIT battery should be changed at the beginning of every cruise that will be performing core orientation. If the battery fails during download, the download itself will slow down immensely and you will lose all survey data past the point where the TransIT battery had insufficient voltage (zeros will be written to the data file).




Figure 16 Flexit new-battery voltage decay at room temperature from repeatedly running \sim 24-hour surveys followed by downloading the tool's data. Deflections in the curve represent the data download periods. The vertical axis translates to over 410 hours of survey time (one record = 6 seconds). See raw survey files (.CSY) for voltage information during actual surveying.